

Land Rover USB Media Interface

Quick Software Upgrade Procedure

Extract the `umia2lr.bin` file to the top directory of a USB flash drive. The file should appear as shown below

Name	Date modified	Type	Size
umia2lr.bin	12/15/2011 6:55 PM	BIN File	1,133 KB

Power the head unit and make sure that the media interface is running and is selected from the Audio CD menu as shown below:



Plug the USB flash drive in the USB connector and the update will start immediately. A screen message will show "Updating Software"



An update takes about 30 seconds. After the update is completed the head unit will refresh the screen and will show the initial screen



To update the Bluetooth software insert a USB flash drive with `umi.dfu` update file in the USB connector and the update will start immediately



The screen will show "BT Software Update" and the track timing will show the progress 0 to 99 on the minutes and 0 to 05 on the seconds



The screen will show "BT Software Update" and the track timing will show the progress 0 to 99 on the minutes and 0 to 05 on the seconds



The screen will show "BT Software Update" and the track timing will show the progress 0 to 99 on the minutes and 0 to 05 on the seconds



An update takes about 7 minutes. After the update is completed the head unit will reset and the screen return to the initial CD screen



To check if the software is updated select CD6 and scroll with SEEK+ until see the Settings menu. Press and hold the SEEK+ to enter



Initial screen will show media player software revision and the next SEEK+ press will show the Bluetooth software revision

